



Table 2.1-3-Calibration Error Concentration Ranges for Tier I

Measurement point	GAS Concentration Ranges CO, ppm		O <sub>2</sub> percent
	Low range <sup>1</sup>	High range	
1	0-40	0-600	0-2
Measurement point	GAS Concentration Ranges CO, ppm		O <sub>2</sub> percent
	Low range 1	High range	
2	60-80	900-1200	8-10
3	140-160	2100-2400	14-16

FOOTNOTE: <sup>1</sup>For Tier II, the CE specifications for the low-range CO CEMS are 0-20%, 30-40%, and 70-80% of twice the permit limit.